

LOCATION	AREA(S) WITH KNOWN ASBESTOS	DATE OF SURVEY	CONDITION OF ACM	TYPE OF ACM	AMOUNT OF ACM
15 Clearview	Tile in kitchen and foyer		Good Condition	2% Chrysotile	
86 Farren Drive	Basement		Good Condition	Chrysotile/Crocidolite	
419 JHR	Tile under kitchen sink		Good Condition	2-3% Chrysotile	
227 Johns Hill Road	Tan linoleum under 227-8-1 & 227-8-2 and subfloor	Full survey completed 6/03/2021	Friable	20% Chrysotile	240 ft <sup>2</sup>
Albright Health Center	126J mop sink splash board	Full survey completed 6/28/2018	Good Condition	30% Chrysotile	
	206E black mastic under tan floor tile		Good Condition	5% Chrysotile	
	245 black mastic under off-white floor tile		Good Condition	2% Chrysotile	
	Restroom next to 248 electrical closet		Good Condition	2% Chrysotile	
	250 black mastic under off-white floor tile		Good Condition	3% Chrysotile	
Campbell Hall	Insulation around generator exhaust (mechanical room)	Full survey completed 8/28/2008	Good Condition	Chrysotile	
	102 floor tile		Good Condition	Chrysotile	
	Hallway floor tile		Good Condition	Chrysotile	
	201C floor tile		Good Condition	Chrysotile	
	201 floor tile near sink		Good Condition	Chrysotile	
	203F Floor tile		Good Condition	Chrysotile	
Callahan Hall	9" floor tiles throughout		Good Condition		
Fine Arts	Roof		Good Condition	1-10% Chrysotile	
Fine Arts (Old Section)	Tan mastic in the following locations: 105A, 142 H, 1st Floor, 2nd Floor, 3rd Floor, and 4th Floor.	Full survey of Fine Arts (old side) 1/3/2023	Good Condition	4% Chrysotile	
Landrum Academic Center	5th Floor Mechanical Room Joint Compound <1%	Full survey completed 9/25/2019	Good Condition	2% Chrysotile	
	204 joint compound	Limited Survey 2/10/2023	Good Condition	≤1% Chrysotile	
	204 cementitious panel in fume hood	Limited Survey 2/10/2023	Good Condition	20% Chrysotile	
Landrum Annex	Print Shop white floor tile and mastic		Good Condition	1-3% Chrysotile	
Nunn Hall	Off-white joint compound in hall by 533 stairs	Full survey completed 5/04/2016	Good Condition	<1% Chrysotile	